

Support Column Damage

- Initial damage inspection on Tuesday, February 20th
- Discovered no support post present
- Closed front entrance







- Contractor arrived
 Wednesday morning to start
 support structure
- Access ports created for inspection
- Structural engineer contacted-due to arrive on February 27th for assessment